



GARMIN G1000 SOFTWARE CONFIGURATION MATRIX
FOR THE MODEL 58/G58

The following is the approved configuration of GARMIN hardware and it's associated software. This document may be subsequently revised by Service Bulletins and/or product upgrades. To confirm the approved configuration for your airplane visit http://www.raytheonaircraft.com/service_support/publications.asp or call Raytheon Aircraft Customer Support at 1-800-429-5372.

G1000 58/G58 Code Loader Card, Garmin Part Number 010-00500-01 (Installs G1000 System Software Version 0500.01)				
Description	Compatible LRU P/N's	System Status Page Name	Software	
			P/N	VER.
GTX 33 Mode S Transponder	011-00779-10	GTX1-GIA1	006-B0172-XX	4.02
		GTX1-GIA2		
GEA 71 Engine/Airframe Unit (Left)	011-00831-00	GEA1-GIA1	006-B0193-04	2.06
		GEA1-GIA2		
GEA 71 Engine/Airframe Unit (Right)	011-00831-00	GEA2-GIA1	006-B0193-04	2.06
		GEA2-GIA2		
GDC 74A ADC	011-00882-00	GDC1-GIA1	006-B0261-03	2.05
		GDC1 FPGA	006-C0055-00	01.05
GMU 44 Magnetometer	011-00870-00	GMU1	006-B0224-00	2.01
		GMU1 FPGA	006-C0048-00	2.00
GDU 1040 PFD	011-00972-03	PFD1	006-B0319-40	6.00
GDU 1043 MFD	011-01079-00	MFD1	006-B0319-40	6.00
GIA 63 No. 1 (1)	011-00781-01	GIA1	006-B0190-30	4.00
		GPS1	006-B0093-xx	3.01
		COM1	006-B0081-xx	7.00
		NAV1	006-B0082-xx	4.00
		GS1	006-B0083-xx	3.00
		GIA1 AUDIO	006-D0425-00	2.00
GIA 63 No. 2 (1)	011-00781-01	GIA2	006-B0190-30	4.00
		GPS2	006-B0093-xx	3.01
		COM2	006-B0081-xx	7.00
		NAV2	006-B0082-xx	4.00
		GS2	006-B0083-xx	3.00
		GIA2 AUDIO	006-D0425-00	2.00

GARMIN G1000 SOFTWARE CONFIGURATION MATRIX
FOR THE MODEL 58/G58

GRS 77 AHRS	011-00868-10	GRS1-GIA1	006-B0223-02	2.03
		GRS1 FPGA	006-C0049-00	02.00
		GRS1 MV DB (4)	006-D0159-00	2000. 00
GMA 1347 Audio Panel	011-00809-00	GMA1-GIA1	006-B0203-06	2.07
		GMA1-GIA2		
GDL 69A Data Link	011-00987-00	GDL69	006-B0317-10	3.00. 00
GSA 81 Autopilot Servo –Qty 4	011-00878-00	(3)	006-B0398-12	2.05
		(2)	006-D0373-00	2.00
GWX 68	011-00883-20	GWX	006-B0266-07	2.01
		GWX FPGA	006-C0042-05	3.00

- (1) Garmin Service Bulletin 0418 must be complied with.
- (2) All LRU entries that begin with GFC1 CERT or CFC2 CERT.
- (3) All LRU entries that begin with GSA.
- (4) GRS1 MV DB Must be updated by Garmin Mandatory Service Bulletin No. 0533 to software part number 006-D0159-01 and Version 2005.00.