



## Safety Communique Index

Communique #	Rev No	Description	Chapter	Date	Effectivity
BJ-CSL-1014-RK-493		Landing Gear - Nose Landing Gear (NLG) Strut Assembly Bearing	32	Jun 2007	Hawker Beechcraft Corporation Model 400A (Hawker 400XP), Serial RK-493
BJ-CSL-1014-RK-494		Landing Gear - Nose Landing Gear (NLG) Strut Assembly Bearing	32	Jun 2007	Hawker Beechcraft Corporation Model 400A (Hawker 400XP), Serial RK-494
BJ-CSL-1014-RK-495		Landing Gear - Nose Landing Gear (NLG) Strut Assembly Bearing	32	Jun 2007	Hawker Beechcraft Corporation Model 400A (Hawker 400XP), Serial RK-495
BJ-CSL-1014-RK-499		Landing Gear - Nose Landing Gear (NLG) and Main Landing Gear	32	Jun 2007	Hawker Beechcraft Corporation Model 400A (Hawker 400XP), Serial RK-499
BJ-CSL-1014-RK-501		Landing Gear - Nose Landing Gear (NLG) and Main Landing Gear	32	Jun 2007	Hawker Beechcraft Corporation Model 400A (Hawker 400XP), Serial RK-501
BJ-ONL-1000	-	Owner Notification Letter for Diamond, Beechjet, and Hawker 400XP Aircraft	70	Oct 2008	DIAMOND / BEECHJET / HAWKER 400XP
CSL HK-CSL-0004	-	Fuel Cross-Feed Shut-Off Valve Cam Anodization (Hard Coat)	28	Jul 2004	800XP aircraft 258632 thru 258644
CSL HWK27-0001	-	New Stall Identification Switches	27	Mar 2003	258541 through 258607 only
CSL HWK-55-0002	-	Flight Data Recorder Failures due to Water Dripping onto the Mounting Tray Connectors	55	Apr 2003	Hawker 800 XP Serial Numbers 258399, 258430, 258439, 258422, 258435, 258457, 258468, 258479, 258499, and 258511
CSL PR-1010	-	Flight controls - Pitch Trim Actuator P/N 390-386004-0005	27	Aug 2007	Model 390 Premier I/IA, Serials RB-62, RB-76, RB-144, RB-147 through RB-150, RB-152, RB-153, RB-155, RB-157 through RB-160, RB-164
CSL PR-CSL-1003	-	Rudder Flow Trigger Rework	27	Dec 2001	RB-4, 6, 7, 8, 10, 19, 20, 21, 22, 23, 24
CSL PR-CSL-1005	-	Attitude and Heading Reference System (AHRS) Upgrade	27	Apr 2005	RB-1, RB-4 and RB-6 thru RB-9
PR-CSL-1011	-	ELEB Landing Gear Non-Conformance	32	Dec 2007	Model 390 Premier I/IA, Serials RB-112, RB-174, RB-175, RB-179, RB-180, RB-181, RB-183.
PR-CSL-1012	-	Sideslip Limit Exceedance Inspection	27	Nov 2007	Model 390 Premier I/IA, Serial RB-159

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 001	-	Control Locks	27	Jan 1972	All aircraft
SC 002	-	Fuel Selector	28	Mar 1972	Bonanza Serials D-1455 thru D-2900 and Bonanza D-1 thru D-1454 with P/N 35-924065 Fuel Selector Unit installed
SC 003	-	BEEHCRAFT Queen Air Powerplant Maintenance	71	Mar 1972	BEEHCRAFT Queen Air 65, 80
SC 004	-	Proper Aileron Replacement in the Field	27	Mar 1972	19, 23, 24
SC 005	-	Aerobatic Fuel System Modification Kit	28	May 1972	BEEHCRAFT 33 thru E33A, K35 thru V35A-TC and 36 Series Aircraft
SC 006	-	Aerobatic Fuel System Modification Kit	28	May 1972	BEEHCRAFT 55 thru D55A, and 95 series aircraft without baffled main fuel cells installed in both wings
SC 007	-	Powerplant, Fuel System, and Electrical Systems Service Publications	71	May 1972	BEEHCRAFT Queen Air 65, 70, 80, 88
SC 008	-	Fuel Selector	28	Aug 1972	19, 23, 24
SC 009	-	Installation of the Beech Model 278 Propeller Pitch Control Mechanism Modification Kit No. 278-0002 S, and FAA A.D. 69-26-4	61	Aug 1972	BEEHCRAFT Bonanzas H35, J35, K35, M35, N35 and P35, Serials D-4866 thru D-7126 and Models A45 (T34A), B45 and D45 (T34B), equipped with a Model 278 propeller
SC 01	-	Control Locks	27	Mar 2008	APPLIES TO ALL HAWKER BEEHCRAFT MODELS
SC 010	-	Replacement of Oil Inlet Port Fitting in Turbocharger Housing	79	Aug 1972	Models V35-TC, V35A-TC and V35B-TC
SC 011	-	Inspection and Repair Procedures on Model 18 Center Section Truss Assemblies	57	Aug 1972	All BEEHCRAFT Model 18 Owners
SC 012	-	Proper Use of the Vernier Throttle Control	76	Aug 1972	Serials MB-265 through MB-561, M-1069 through M-1411, MA-273 through MA-368 and MC-1 and after equipped with the Vernier Throttle Control. Serials prior to M-1069, MB-265 and MA-273 with kits 23-9003 S, 23-9003-1 S, 23-9003-2 S or 23-9003-3 S installed.
SC 013	-	Secure the Aft Partition Door (if installed) During Takeoffs and Landings	52	Oct 1972	All BEEHCRAFT Model 18 Owners

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 014	1	Inspection of Hartzell Propellers Propellers, HC92WK2B and HC92ZK2B/8447A-12A/8447-12R, on BEECHCRAFT Travel Airs	61	Feb 1973	BEECHCRAFT Travel Air 95, B95, B95A, D95A and E95 Aircraft
SC 015	-	Main Fuel Tank Filler Opening	11	Jan 1973	Beechcraft Bonanza 33, 35,36 series: D-1 thru D-9419; CD-1 thru CD-1304; CE-1 thru CE-413; CJ-1 thru CJ-34; E-1 thru E-381
SC 016	-	Main Fuel Tank Filler Openings	11	Jan 1973	55 and 95 Series (TC-1 thru TC-1505; TE-1 thru TE-893; TF-1 thru TF-70; TH-1 thru TH-285; TD-1 thru TD-721)
SC 017	-	Elevator Stop Bolt	27	Jun 1973	Models C-90, serials LJ-552 thru LJ-587; Model B-80, serials LD-452 thru LD-467; Model E-90, serials LW-1 thru LW-55
SC 018	-	Century I Autopilot Installation	22	Jun 1973	Models 23, A23, A23A, B23, C23, A23-19, 19A, MI9A, B19, A23-24, A24, A24R
SC 019	-	Inspection of the Exhaust Muffler	78	Jun 1973	M-1 and after; MB-1 and after; MA-1 and after; MC-2 and after
SC 020	-	Testing for Intentional Spins, Other Acrobatic Manuevers per FAA prescribed standard	00	Jun 1973	B-19 series MB-481 and after; Model 23 series M-1285 and after
SC 021	-	Internally Lighted Altimeter	34	Jul 1973	BONANZAS: D-9398 thru D-9520; CD-1301; CE-405 thru CE-456; E-368 thru E-460; CJ-31 thru CJ-39; BARONS: TH-269 thru TH-366; TE-884 thru TE-934; TC-1490 thru TC-1592
SC 022	-	Beechcraft Model B19 Sport Climb Performance	92	Oct 1973	B19 Sport, Serials MB-481 thru MB-616
SC 023	-	Beechcraft Model B19 Sport Climb Performance	92	Nov 1973	B19 Sport, Serials MB-481 thru MB-616
SC 024	-	Information for Pilots and Owners	00	Dec 1973	All BEECHCRAFT Airplanes
SC 025	-	Fuel Selector Valves on the Aircraft Models Specified Above	28	Feb 1974	Baron Model 58 serial #TH-177 and after; Duke Model 60 serial #P-163 and after, and all Duke, Baron 58 and 56TC airplanes with replaced fuel selector valves within the last 2 years
SC 026	-	Fuel Selector Valve	28	May 1974	Serials MB-1 thru MB-520; M-2 thru M-1361; MA-1 thru MA-368; MC-1 thru MC-95; MB-521 thru MB-616; M-1362 thru M-1485; MC-96 thru MC-180

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 027	-	Fuel Quantity Indication System	28	Aug 1974	All BEEHCRAFT airplanes, specifically MB-655 thru MB-729; M-1517 thru MB-1597; MC-199, MC-209 thru MC-302
SC 028	-	Fuel Selector Valve Handle	28	Sep 1974	D-2901 thru D-5330 except D-5062 and earlier Bonanzas with Kit No. 35-576 S or 35-924030 installed.
SC 029	-	Restriction of Intentional Spins	53	Sep 1974	M-1, M-2, M-4 thru M-554; MB-1 thru MB-288; MB-289 thru MB-460; MB-461 thru MB-480; M-1095 thru M-1284
SC 030	-	Open Bleed Valve in PT6A-41 Engine	72	Oct 1974	Super King Air 200 aircraft
SC 031	1	Bendix Fuel Injector System Inspection	28	Jan 1975	95, 24R, A23-24, A24, B24R
SC 032	1	Icing (this communique supersedes and cancels Safety Communique No. 32 dated February 25, 1975.)	30	Jun 1986	Model 18, Twin Bonanza, Baron, Duke, Queen Air, King Air, Super King Air, 99 Airliner, 1900 Airliner
SC 033	-	Replacement of Oil Inlet Port Fitting, Oil Inlet Adapter and Exhaust Wastegate Elbow Assembly, and Inspection Of Complete Turbocharger System	79	Apr 1975	Models V35-TC, V35A-TC, V35B-TC
SC 035	-	PT6 Engine Power Turbine Overspeed	72	Apr 1975	King Air 90 and Beechcraft 99 using PT6A engines
SC 036	-	Beechcraft Model 18's - X-Ray Inspections on Specified Wing Structures	57	Apr 1975	All Beechcraft Model 18 series
SC 037	-	Collins AP-105 Autopilot	22	May 1975	BB-2, -7, -8, -9, -11, -13, -14, -15, -21, -22, -26, -24, -28, -31, -32, -33, -34, -36, -38, -39, -40, -44, -45, -47, -51, -53, -55, -56, -62
SC 038	-	Safety Information	00	Jan 1976	All Owners of BEEHCRAFT Airplanes on the FAA Registration List
SC 039	-	Cabin Door - Pressurized Airplanes	52	Aug 1975	All King Air, Queen Air 88 and Duke series
SC 040	-	Flight Control System - Lubrication Of Moving Components	27	Jul 1975	All Beechcraft Models 19, 23, 24, 24R series
SC 041	-	Inspection of Buss Bar/Terminal Board Connections on Reverse Current Relay Panel Assemblies	24	Jul 1975	LJ-597, LJ-598, LJ-599, LJ-640 thru LJ-662; LJ-667, LJ-668, and LJ-699; LW-120 thru LW-150; B-208 thru B-216 and B-218 thru B-221

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 042	-	Operating Instructions for Air Charged Propellers	61	Oct 1975	TC-1416 and after; TE-850 and after; TG-1 thru TG-94; TH-195 thru TH-209 and TH-211 and after equipped with 2-blade propellers; TH-182 and after equipped with op 3-blade propellers; P-3 and after; earlier models with air charged propellers per STC SA773CE
SC 043	-	Engine Chip Detector Lights	33	Oct 1975	BB-2 and after
SC 044	-	Oil Filter Adapters and New Type Oil Filter	79	Feb 1976	TJ-4 and after, TH-615 and after, TE-1044 and after; D-9757 and after, E-670 and after, CE-572 and after, CJ-86 and after
SC 045	-	Bendix Ignition Switches	74	Feb 1976	Musketeer, Sport, Sundowner, Sierra, Bonanza, Baron, Duke, Travel Air, Queen Air with Bendix Rotate-to-Start Ignition Switches
SC 046	1	Implementation of Safe One Engine Inoperative Speed And Procedure For Demonstration Of Vmca	92	Nov 1976	Travel Air 95, B95, B95A, E95; Baron 55, A55, B55, C55, D55, E55, 56TC, A56TC, 58, 58P
SC 047	-	Electrical System - Battery and Alternator Operations	24	Nov 1976	Beechcraft Models 19, 23, 24, and 24R
SC 048	-	Beech Queen Air and Twin Bonanza Powerplant and Powerplant Systems Maintenance	71	Oct 1977	Queen Air, Twin Bonanza
SC 049	-	Emergency Procedure - Loss of Electrical Power in Flight	24	Mar 1976	Beechcraft Duchess Model 76
SC 051	1	Wing Attach Bolt and Nut	57	Feb 1980	BB-2 thru B-448, BT-1 thru BT-3; U-55, U-67, U-87, GM-1 thru GM-71 and GM-78; GP-1 thru GP-6
SC 052	-	Wing Bolt and Nut	57	Feb 1980	BB-449 thru BB-599, BB-601 thru BB-606, BB-608 thru BB-613, BB-620, BT-4 thru BT-10, BL-1 thru BL-5, LA-2 thru LA-15, LA-22, LA-23, LA-25, LA-26, LA-28, U-40, U-73, U-90, U-96, U-126, U-152, U-153
SC 053	-	Environmental System - Cabin Heat - Detection of Carbon Monoxide	21	Mar 1980	Serials WA-1 and after
SC 054	-	Icing Certification and Capabilities o the Baron Class of Airplanes	30	Jul 1980	Not specified
SC 055	-	Excessive Speed Accidents - Beechcraft Models 33, 35, and 36	92	Aug 1980	Debonairs, Bonanzas

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 056	-	Availability of Shoulder Harness Kits for Existing Models of Aircraft	25	Oct 1980	KA, QA, Airliner, Duke, Baron, Travel Air, Bonanza, Debonair, Sierra, Sundowner, Sport, Musketeer
SC 057	-	Elevator Trim Tab Freezing - Exposure of Aircraft to High-Pressure Soap-And-Water Washing and Intense Rain	30	May 1981	All Beechcraft Airplanes
SC 058	-	Turbocharger Exhaust Pipe	78	Jun 1981	Beechcraft Models 58TC, 58P
SC 059	-	Wing Spar -Tension Bolt Assembly and Saunders Strap Modification	57	Jun 1981	All King Air and Queen Air Models
SC 060	-	Safety Information	00	Jun 1981	All Beechcraft Airplanes
SC 061	-	Safety Information	00	Jul 1981	Beechcraft Model B99 Airliner
SC 062	-	Flight Controls - Inspection off Elevator Cable Routing	27	Jan 1982	ME-1 thru ME-435
SC 063	-	Fuel System - Inspection For Security of Gascolator Drain Bolt	28	Aug 1982	WA-1 thru WA-312
SC 064	-	Air Conditioner Clutch Assembly	21	Oct 1982	P-1 & after
SC 065	-	Wake Turbulence Strikes Again	00	Apr 1983	All Beechcraft Airplanes
SC 066	-	Woodward Service Bulletin 33581	61	Sep 1983	ME-1, ME-3 thru ME-395; ME-397 thru ME-404; ME-406; ME-408 thru ME-411; ME-413; ME-414; ME-416 thru ME-419; ME-421; ME-423; ME-425 thru ME-428; ME-430; ME-432 and ME-437
SC 067	-	Difference between the reservoir tank and baffled fuel cell	28	Apr 1985	CJ-31 th CJ-155; TC-1608 th TC-2002 exc TC-1970; TE-938, TE-943 th TE-1083 exc TE-1081; TH-385 th TH-772 exc TH-766. D-5726 th D-9068, CD-1 th CD-1304, CE-1th CE-289, CJ-1 th CJ-30, E-1 th E-184, TD-2 thTD-721, TC-1th TC-834 w/fuel cell reservoir kit
SC 068	1	Cabin Door Operation/Openings	52	Mar 1987	Bonanza, Baron, Travel Air
SC 069	-	Cylinder Barrel Cracking	72	Mar 1986	Models A36, 55, 58, 58P, 58TC
SC 070	-	Hydraulic Landing Gear - Servicing Accumulator	32	Mar 1986	LJ-1063 & after; LA-226 & after; BB-1158, BB-1167, BB-1193 & after; BL-73 & after; 300 series, 99 series, 1900 series
SC 071	-	Starter Engaged Warning Lights	33	Apr 1986	Mitsubishi Diamond Model MU-300, MU-300-10
SC 072	-	Quick-Clamp Cockpit Work Station	25	Sep 1986	Bonanzas, Barons

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 073	-	Beechcraft Baron and Bonanza Seat Belts (Installed 1984 and after)	25	Sep 1986	E-2104, E-2111 and after; EA-320, EA-389 and after; CJ-156 and after; CE-1024 and after; TH-1389, TH-1396 and after; TJ-436, TJ-444 and after; TK-151 and after
SC 074	-	Mandatory Operating Restrictions	04	Oct 1986	D-1 thru D-10403
SC 075	-	Aft Cowling Door Upper Latches (Thumb Latches)	71	Jan 1987	FA-106, FA-110, FA-112 and after
SC 076	-	Airborne Service Letter No. 31	36	Mar 1987	Models 19, 23, 24, 77, 33, 35, 36
SC 077	1	Cabin Door Operation/Openings	52	Aug 1990	Models 23, A23, A23A, A23-19, A23-24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R, 76, 77
SC 078	-	Model 1900 Main Gear Wheel Assembly, P/N 114-8003-1 and 114-8007-1	32	Mar 1987	1900, 1900C
SC 079	-	The Effects of Facial Hair on the Efficiency of Oxygen Masks	35	Jun 1987	All BEECHCRAFT Models
SC 080	-	Use of Automobile Type Gasoline in Beech Aircraft	28	Jul 1987	Models 18, 19, 23, 24, 33, 35, 36, 45, 50, 55, 56, 58, 60, 65, 70, 76, 77, 80, 88, 95
SC 081	-	Fuel System Water Contamination	28	Jul 1987	Models 18, 19, 23, 24, 33, 35, 36, 45, 50, 55, 56, 58, 60, 65, 70, 76, 77, 80, 88, 95
SC 082	1	Hartzell Service Bulletin No. 153	61	Aug 1987	BE-1 and after
SC 083	-	Broken Counterweight Bolts - McCauley Service Bulletin 166A	61	Sep 1987	BB-1193 and after; BL-124 and after
SC 085	-	Pilot's Operating Handbook/Manual - Accelerate-Stop Distance Chart	92	Oct 1987	LJ-318 thru LJ-1146 except C90A's with maximum takeoff weight of 10,100 lbs.
SC 086	-	Discontinuance of Spanish Publications	00	Nov 1987	All Beechcraft Airplanes
SC 087	-	Mandatory Inspection of Air Conditioner Compressor Drive	21	Dec 1987	D-7310 thru D-10403; CE-1 thru CE-1148; CJ-1 thru CJ-178; E-1 thru E-2376; EA-1 thru EA-465; TK-1 thru TK-151; TJ-3 thru TJ-497
SC 088	-	Mandatory Removal of Continental Oil Filters, Part Numbers 649309 and 649310 (Pro-Tech)	79	Feb 1988	D-7310 thru D-10403; CE-1 thru CE-1209; CJ-1 thru CJ-178; E-1 thru E-2402; EA-1 thru EA-473; TE-1 thru TE-1201; TH-1 thru TH-1531; TK-1 thru TK-151; TJ-3 thru TJ-497
SC 089	-	Operation of Auxiliary Fuel Pump on Model A36TC and B36TC Bonanzas	28	Mar 1988	Not specified

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 090	-	Wing Spars	57	Apr 1988	BB-2, BB-6 thru BB-1050, BB-1052 thru BB-1090; FA-1 thru FA-230
SC 091	-	Nose Landing Gear Door	32	May 1989	ME-1 thru ME-437
SC 092	-	JT15D-5 HMU Alert Service Bulletins	72	Nov 1990	Mitsubishi Diamond II, Beechjet Model 400 Airplanes
SC 093	-	Woodward Unfeathering Accumulators, Part Numbers 8907-001 and 8907-021	61	Dec 1990	TG-2 thru TG-94; TJ-3 thru TJ-437; TK-1 thru TK-151; P-3 thru P-596; ME-1 thru ME-437
SC 094	-	Collins EFIS-85B (-14) And APS-65H Systems	22	Jun 1991	BB-1349 and after; FA-205 and after; FL-1 and after; FM-1 and after; UC-73 and after
SC 095	-	Rudder Moisture Drains	27	Jun 1991	FL-1 & after; FM-1 & after; FN-1 & after
SC 096	-	Potential In-flight Freeze up of the Instrument Air System	34	Oct 1991	Model 1900 Airliners
SC 097	1	Hazards of Ice or Snow Accumulation on Forward Wing Prior to Takeoff	30	Dec 1991	NC-1 & after
SC 098	-	Control Surface Inspections for Corrosion and Cracks	27	Apr 1992	All Beechcraft models
SC 099	-	Wing Attach Bolts And Nuts	57	Jun 1992	GM-1 thru GM-142; GP-1 thru GP-50
SC 100	-	1900D Style Engine Truss	71	Jun 1993	UA-1 & after; UB-1 & after; UC-1 & after; UE-1 & after
SC 101	-	Main Circuit Breaker Panel Wiring Protection	39	Jul 1993	RK-45 and RK-49 thru RK-77; TT-01 thru TT-42, TT-44
SC 102	-	Flutter - Inspection of Control Surfaces	27	Sep 1993	All Beechcraft Models
SC 103	-	Maintenance Practices on All Beechcraft Airplanes With Hydraulic Landing Gear Actuating Systems	32	Sep 1993	Models 24R, 76, 90, 99, 200, 300, 350, 400, 1900 & 2000
SC 104	1	Starship Wheel Bearings	32	Dec 1993	NC-1 & after
SC 105	-	Inspection of Nose Avionics Compartment Wiring	39	Sep 1993	UE-1 & after
SC 106	-	Wheel Brake Systems	32	Sep 1993	Diamond II MU300-10; 400, 400A, 400T (T-1A) Airplanes
SC 107	-	Anti-Skid and Wheel Brake Systems	32	Dec 1993	Diamond II MU300-10; 400, 400A, 400T (T-1A) Airplanes

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 108	-	Hazards of Ice, Frost or Snow Accumulation on your Airplane Prior to Takeoff	30	Feb 1994	NC-1 & after
SC 109	-	Horizontal Stabilizer Icing	30	Jul 1994	MU300-10; 400, 400A, 400T (T-1A and TX) Airplanes
SC 110	-	Electrical Harness Chafing	39	Jul 1994	NC-4 thru NC-53
SC 111	-	Inspection of Rudder Bellcrank Support Attachment Bolts	27	Dec 1994	UE-1 & after
SC 112	-	Inspection of Elevator Trim Tab Control Cables	27	Jan 1995	UE-1 & after
SC 113	-	Inspection of Spoiler Flight Control System	27	Mar 1995	RK-1 thru RK-96
SC 114	-	Inspection of Fuel Transfer Tube Assemblies	28	Apr 1995	UC-1 thru UC-174; UD-1 thru UD-6; UE-1 thru UE-136, UE-138
SC 115	-	Dangers of Handling Asbestos	00	Jul 1995	All Beech Airplane Models
SC 116	-	Cabin Door, Baggage Door, Engine Cowling and Fuel Cap Latching and Security	52	Oct 1995	All Beech Airplane Models
SC 117	-	Uncommanded Reduction in Engine Thrust	71	Oct 1995	BAe 125-1000 and Hawker 100
SC 118	-	Fluctuation of Fuel Quantity Indication(s) During HF Transmissions	28	Feb 1996	259006, 259009, 259011, 259013, 259014, 259016, 259017, 259020, 259023, 259033, 259035, 259036, 259038, 259039, 259040, 259041, 259042, 259043, 259045, 259046, 259047
SC 119	-	Inboard and Outboard Spoiler Hinge Assembly Inspection	27	Oct 1995	RK-1 & after, 400T
SC 120	-	Fuel Filter Assembly Inspection/Replacement	28	Dec 1995	UC-1 thru UC-174; UE-1 thru UE-185; UD-1 thru UD-6
SC 121	-	Fuel Filter Assembly Inspection/Replacement	28	Dec 1995	NC-4 thru NC-53
SC 123	-	Lowering of the Landing Gear by Use of the Auxiliary Hydraulic System	32	Apr 1996	Hawker 1000, Hawker 800, Hawker 800XP and all 125 Series Aircraft
SC 124	-	Autopilot System Safety Procedures	22	Jun 1996	All Beech Airplane Models
SC 125	-	Limitations and Procedures for Flights Encountering Severe Icing Conditions (for airplanes approved for flight in icing conditions)	30	Jun 1996	All Beech Airplane Models
SC 126	-	MIL-H-6000B Hoses Manufactured by Buckeye Rubber Products Company in Lima, Ohio	28	Aug 1996	All Beech Airplane Models

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 127	-	Ventilation Blower Motor Operational Procedures	21	Aug 1996	Beech 1900
SC 128	-	Inspection and Lubrication of Main Landing Gear Actuator Rod-Ends	32	Oct 1996	Beech 1900
SC 129	-	MIL-H-6000B Hoses Manufactured by Buckeye Rubber Products Inc. in Lima, Ohio	28	Sep 1996	All Beech Airplane Models
SC 130	-	Inspection of Lap Belts with a Detachable, Single Shoulder Harness Restraint	25	Dec 1996	18, 19, 23, 24, 33, 35, 36, 50, 55, 56, 58, 60, 65, 70, 76, 77, 80, 88, 90, 100, 200, 300, 400A, 1900C (with Executive Seating) and 2000 series
SC 131	-	Inspection of Lap Belts with a Detachable, Single Shoulder Harness Restraint	25	Feb 1997	DH/BH/HS/BAe 125 Series 1 to 1000, Hawker 800 and Hawker 1000
SC 132	-	Inspection of the Attachment Screws for the Airstair Door Interior Handle Bellcrank Assembly	52	Feb 1997	Beech 1900D Airliners
SC 133	-	Windshield Electrical Fault Procedures	56	Apr 1997	Beech 99, B200HDC (1300), 1900
SC 134	-	Windshield Electrical Fault Procedures	56	Apr 1997	C90A, F90, 200, B200, 300 and B300
SC 136	-	Emergency Exit Inspection for Clearance	52	May 1997	1900/1900C and C-12J
SC 137	1	Inspection of the Outboard Flap Attachment Brackets and Roller Bearings	27	Dec 1997	1900 Series, C-12J
SC 138	-	Model 99 Series Landing Gear Retraction System Power Pack Replacement	32	Jun 1997	99 Series
SC 140	-	Leland Static Inverter (P/N ASH664-1PF or ASH664-1P) Reset Procedure	24	Jul 1997	258001 thru 258150; 258152 thru 258158; 258160 & after
SC 141	-	EPA Engine Fuel Nozzle Purge System	73	Apr 1998	LJ-901 & after; LW-334 & after; LA-57 & after Airplanes Equipped with EPA Fuel Purge Systems
SC 142	-	Inspection of Cockpit Side ("D") Windows	56	Nov 1997	65-90, B90, C90, E90, H90 (T44A) and 100 Series
SC 143	-	Elevator Control Cable Inspection	27	Oct 1997	LJ-502 thru LJ-1400; LW-1 thru LW-347; LA-1 thru LA-236; LL-1 thru LL-61
SC 144	-	Elevator Adjustment Weights and Attachment Screws	27	Dec 1997	F90, 200, B200, 300, B300, 1900 Airliners

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 145	-	Windshield Heat Terminal Blocks and Electrical Wiring Inspection - Windshield Electrical Fault Emergency Procedures	56	Jan 1998	400, 400A, 400T (T-1A, TX), MU-300
SC 146	-	Inspect Crane/Lear/Romec Engine-Driven Fuel Pumps for Leaks	73	Apr 1998	18, 56TC, 60 Series, 80 Series
SC 147	-	Spin Avoidance and Spin Recovery Characteristics	00	Mar 1998	Beech Barons
SC 148	-	Engine Truss Attachment Bolt Inspection	71	May 1998	Beech 1900 Series Airliners and Model C-12J Airplanes
SC 149	1	Loss of Aileron and Elevator Control	27	Nov 1998	A36, B36TC, 58, C90A, B200, B300, 1900D
SC 150	-	Main Landing Gear Lock Link Assembly Inspection	32	Sep 1998	NC-4 thru NC-53
SC 151	-	Frigid Weather Preparation	30	Oct 1998	Beech 1900 Airliner
SC 152	1	Propeller Hazards During Ground Operations	61	Feb 1999	Beech 1900 Airliner Series
SC 153	-	Precautions Regarding the Use of the Aft Cabin Heat Vent Outlet	21	Nov 1998	RK-98, RK-110 & after
SC 154	-	New Inspection and Maintenance Requirements for Main Landing Gear Wheel Tie Bolts and Nuts	32	Dec 1998	All Hawker/125 Series with Dunlop Wheels
SC 155	1	Cracked Propeller Blade	61	Dec 2001	NC-4 thru NC-53
SC 156	-	Inspection of Engine P3 Condensation Trap to Prevent Possible Engine Power Loss	73	Feb 1999	RJ-1 thru RJ-65, RK-1 & after; TT-1 thru TT-180, TX-1 thru TX-9
SC 157	-	Rosemount Pitot Probe Icing	30	Feb 1999	All BAe/Hawker 600, 700, 800 and 800XP Series
SC 158	-	Upper Flap Cove Panel Inspection	27	Mar 1999	NC-4 thru NC-53
SC 159	1	Teledyne Continental Motors (TCM) Crankshaft Fractures	72	Apr 1999	Bonanza, Baron, Debonair/Bonanza
SC 160	-	Worn Engine Condition Lever Low-Idle Catch Gates	76	Apr 1999	All Beech 90 Series, 100, A100, 200 Series, 300 Series, 99 Series, 1900 Series, 2000
SC 161	1	Landing Gear Trunnion Bolt Installation	32	Mar 2002	UE-1 thru UE-344, UE-348 thru UE-350, UE-353, and UE-359 thru UE-431
SC 162	2	Wing Spar Assembly And Wing Attachment Fitting Fatigue Fractures - Additional Information, Grounding of Airplanes	57	Jul 1999	G-3 thru G-6; G-7 and after; CG-1 and after; BG-1 and after; 34-1 thru 34-125; Bonanza 35 thru G35

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 163	-	Corrosion Control and Inspection	51	Jul 1999	UA-2 and UA-3; UB-1 thru UB-74, and UC-1 thru UC-174; UD-1 thru UD-6; UE-1 and after
SC 164	1	Fire Caused by Electric Wire Chafing Fuel Line and Fire Extinguisher	39	Feb 2000	UA-2 and UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UE-1 thru UE-384
SC 165	-	Pratt & Whitney Canada Service Information Letter No. PT6A-075, Inspection of Second Stage Power Turbine Blades Pre/Post P&WC SB No. 14172	72	Mar 2000	UE-1 and after; NC-4 and after
SC 167	-	Main Landing Gear Actuator Lug Separation	32	Nov 1999	All Hawker Series Airplanes
SC 168	-	Passenger Oxygen Mask Stowage	35	Jan 1999	All Raytheon Aircraft Models with Deployable Passenger Oxygen Mask Systems
SC 169	-	Wing Flap Safety System	27	Feb 2000	UA-2 and UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UE-1 and after
SC 170	-	Airstair Door Handrail Cable Anchor Brackets	52	Jul 2000	UE-1 thru UE-415
SC 172	-	Electrical Discharge Damage to the Engine No. One Bearing	72	Dec 2000	UE-1 & after
SC 173	-	Operational Procedures for Ventilation Blowers	21	Jan 2001	UA-2 and UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UD-1 & after
SC 174	-	Beechjet Roll Trim Operation	27	Nov 2000	RK-45, RK-49 and after; TT-1 thru TT-180; TX-1 thru TX-10
SC 176	-	KFC-225 Autopilot System	22	Jan 2001	E-3157, E-3200, E-3218 thru E-3293, E-3295, and E-3297 thru E-3367; EA-611, EA-620, EA-629 thru EA-662, EA-664; TH-1841, TH-1870, TH-1884 thru TH-1970; TH-1973 and TH-1974
SC 178	-	Compliance of Mandatory Service Bulletin No. 52-3417, Replacement of the Upper Anchor Brackets for the Airstair Door Forward and Aft Handrail Cables	52	Feb 2001	UE-1 thru UE-415
SC 179	-	Main Landing Gear Downlock Dimensions	32	Apr 2001	All King Air Model Aircraft Equipped with Hydraulic Actuated Landing Gear Systems
SC 180	-	Elevator/Rudder Control System Binding	27	Apr 2001	RK-1 and after; TT-1 thru TT-180; TX-1 thru TX-10
SC 182	-	Flap Drive Cables	27	May 2001	Baron, Bonanza, Travel Air
SC 184	-	Beechjet Brake Mixing Valves P/N C100169	32	Jun 2001	RK-287 thru RK-302, RK-305

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 185	-	Flight Control "T" Column Inspection	27	Aug 2001	LJ-1440 thru LJ-1640, BB-1536 thru BB-1770, BL-141, BT-39 thru BT-43, FL-141 thru FL-329, FM-9, FM-10, UE-226 thru UE-422; FE-32, FE-35, FE-36; BW-18 thru BW-29
SC 186	-	Angle of Attack (AOA) Transmitter Sticking	31	Aug 2001	RK-45, RK-49 and after; TT-1 thru TT-180; TX-1 and after
SC 187	-	KFC-225 Automatic Flight Control System (AFCS)	22	Nov 2001	E-3157, E-3200, E-3218 thru E-3347, E-3349 thru E-3382, E-3385, E-3388, E-3389, E-3392, E-3401, E-3402, EA-611, EA-620, EA-629 thru EA-671, EA-674, TH-1841, TH-1870, TH-1884 thru TH-1981, TH-1986, TH-1988, TH-1989, TH-1995, TH-2005, TH-2009, TH-2011
SC 188	-	Loss of Valid Air Data Information	34	Nov 2001	A003SA thru A091SA; A1001SA thru A1011SA; RJ-1 thru RJ-65; RK-1 and after; TT-1 thru TT-180; TX-1 and after
SC 189	1	Inspection- Engine Carry Through Mount Bracket Cracks	71	Jan 2002	RJ-1 thru RJ-65; RK-1 and after; TT-1 thru TT-180; TX-1 thru TX-11; A003SA thru A091SA; A1001SA thru A1010SA
SC 190	-	Cabin Chair Hydroloks	25	Jan 2002	DH/BH/HS/Bae 125 series 1-1000, Hawker 800, 800XP, 1000 with Cabin Chair Part Numbers 3012, 3032 AND 3043 Installed with Hydroloks April 30 to August 20, 1999
SC 191	-	Improper Collins Flight Management System (FMS) Approach Mode Operation	34	Feb 2002	400A, 400T (T-1A), 400T (TX) equipped with AMS-5000 , Hawker 800XP equipped with Proline 21 and FMS-6000, 390 Premier I equipped with FMS-3000
SC 192	-	Spin Avoidance and Spin Recovery Characteristics	00	Feb 2002	All Beech Baron Airplanes
SC 195	-	Inertial Vane Linkage Inspection	71	Apr 2002	UE-1 and after
SC 196	-	Inertial Vane Linkage Inspection	71	May 2002	FE-1 thru FE-36; FA-1 thru FA-230, FF-1 thru FF-19; FL-1 thru FL-334; FM-1 thru FM-9, FN-1
SC 197	-	Main Landing Gear Drag Leg Center Pivot Bolts	32	May 2002	UA-2 and UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UE-1 and after
SC 198	-	Electrical Bonding Between the Radome Diverter Strip and Aircraft Ground	20	May 2002	RB-4 thru RB-15, RB-19 thru RB-32, RB-34

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 199	-	Pneumatic Manifold Check Valve Functional Test	36	Jun 2002	TC-2003 thru TC-2456; TD-708 thru TD-721; TE-452 thru TE-767 thru TE-1201; TG-52 thru TG-94; TH-1 & after; TJ-3 thru TJ-497; TK-1 thru TK-151; P-4 thru P-596; LD-362 thru LD-511; LC-271 thru LC-335; LB-1 thru LB-35; ME-1 thru ME-437
SC 200	-	Lubrication of Mechanical Joints	32	Aug 2002	1900, 1900C, 1900C (C-12J) and 1900D Series
SC 201	-	Wing Fuel System Probe Clearance	28	Jul 2002	RB-4 thru RB-15, RB-19 thru RB-32, RB-34 thru RB-40
SC 202	-	Loose Engine Cowling Truss Attachment Brackets	71	Aug 2002	UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UE-1 thru UE-436
SC 205	-	Adaptive Flight Display (AFD) Potential Anomalies	31	Aug 2002	RB-4 thru RB-15, RB-19 thru RB-32, RB-34 thru RB-39; 258278, 258541, 258556, 258567 thru 258578 equipped with Proline 21 System
SC 206	-	Elevator Cable Inspection	27	Aug 2002	RB-4 thru RB-15, RB-19 thru RB-32, RB-34 thru RB-39
SC 207	-	Cabin Seat Base Rail Attach Fitting Inspection	25	Oct 2002	RK-98, RK-110 thru RK-338, RK-340 thru RK-344; TX-11, TX-12
SC 208	-	Low Fuel Quantity Annunciation	28	Aug 2002	RB-1 & after
SC 209	-	Essential Bus Relay (24K5) Corrosion	39	Aug 2002	RB-4 thru RB-39
SC 210	-	Cockpit Oxygen Gage	35	Sep 2002	RB-4 thru RB-15, RB-19 thru RB-32, RB-34 thru RB-40
SC 211	-	Battery Electrical Connector	24	Sep 2002	DH/BH/HS/Bae 125 Series 1-1000, Hawker 800, 800XP, 1000 Aircraft with Saft Battery Part Numbers 23491 and 23491-3
SC 212	-	Pre-Takeoff Checklist when Icing Flight is Anticipated	30	Oct 2002	LJ-1 and after, LW-1 thru LW-347
SC 213	-	Inspection of Fuel System Motive Flow Check Valve	28	Oct 2002	UA-3; UB-1 thru UB-74, UC-1 thru UC-174; UD-1 thru UD-6; UE-1 thru UE-439
SC 214	-	Disablement of Cabin Entertainment System	25	Dec 2002	258377, 258397 thru 258400, 258402 thru 258567, 258569 thru 258586, 258588
SC 215	-	Pulselite System Anomaly	33	Feb 2003	BAe 125-800, Hawker 800, Hawker 800XP
SC 216	-	Elevator Control System Rigging Inspection	27	Jan 2003	1900, 1900C, 1900C (C-12J), 1900D

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 218	-	Possible Erroneous Glide Slope Indications On The RNZ-850/851 Integrated Nav Unit With MOD "L" NV-850 Nav Receiver Modules	34	Feb 2003	Hawker Bae 125 Series 800, Bae 125 Series 1000, Hawker 800, 800XP and 1000 Equipped with Honeywell RNZ-850/851 Integrated Nav Units
SC 219	-	Dual-Head Fire Extinguisher Electrical Connectors	26	Mar 2003	258272, 258274, 258276, 258277, 258278, 258281, 258283 thru 258304, 258306 thru 258615
SC 220	-	Lift Dump Fail Annunciation	27	Mar 2003	RB-2 thru RB-58
SC 222	-	RH and LH (24K1 and 24K2) Generator Bus and Essential Bus Relay (24K5) Water Ingression	39	Apr 2003	RB-4 thru RB-15, RB-17 thru RB-56
SC 223	-	Alternate Gear Release Handle Security	32	Apr 2003	RB-1, RB-4 thru RB-15, RB-17 thru RB-60, RB-63 thru RB-65
SC 224	-	Hydraulic Reservoir Overboard Check Valve	29	Jun 2003	RB-4 thru RB-15, RB-17 thru RB-69
SC 225	-	Aileron System Control Sprocket	27	Jun 2003	1900/C/D, 200T, 200CT, B200, B200C, B200T, B200CT, B300, B300C, 300 (FAA), 300LW, A100-1, A200, A200C, A200CT, RC-12D/H/K/N/P/Q, C-12F, C-12R, UC-12M, RC-12M, UC-12F, RC-12F, FWC-12D
SC 226	-	Service Bulletin No. 21-142-3514A - Introduction of Improved Airesearch Fan Venturi P/N 132322-3-1	21	Jun 2003	125/Hawker Series 1-700, 800, 1000
SC 227	-	Forward and Aft Baggage, Avionics and Maintenance Bay Doors	52	Jul 2003	RB-1 & after
SC 228	-	Engine Controls Cross Shaft Hardware	77	Jul 2003	90, F90, 100, 200, 300, B300, 99, 1900 Series
SC 231	-	Emergency Radio Bus Operation	23	Sep 2003	258541, 258556, 258567 thru 258591, 258594 thru 258598, 258600 thru 258602, 258604, 258605, 258607, 258608
SC 232	-	Fire Extinguisher Nozzle Assembly Inspection	26	Sep 2003	RB-1, RB-4 thru RB-15, RB-17 thru RB-71
SC 233	-	DA Circuit Breaker Panel Access	39	Oct 2003	Hawker 800XP Serials
SC 234	-	Elevator Trim Tab Cable Installation	27	Sep 2003	1900, 1900C, 1900C (C-12J), 1900D
SC 235	-	Control Column Wire Harness Inspection	39	Oct 2003	RB-1, RB-4 thru RB-15, RB-17 thru RB-80, RB-82, RB-84
SC 236	-	Flap Actuators	27	Oct 2003	RB-4 thru RB-15, RB-17 thru RB-80, RB-82, RB-84

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 237	-	Elevator Trim Operational Checks	27	Oct 2003	1900, 1900C, 1900C (C-12J), 1900D
SC 239	-	Main Landing Gear (MLG) Wheel Nut Torquing	32	Nov 2003	LJ-1 & after, LW-1 thru LW-347, LM-1 thru LM-141, LU-1 thru LU-16, LL-1 thru LL-61
SC 240	-	Main Entry Door Folding Handrail Assembly	52	Dec 2003	Hawker Bae. 125 Series 800A, BAE. 125 Series 800B, Hawker 800 and Hawker 800XP if Equipped with Folding Handrail Assembly
SC 242	-	Landing Gear Alternate Extension Aft Quadrant Inspection	32	Apr 2004	RB-1, RB-4 thru RB-86
SC 243	-	Elevator Trim Tab To Actuator Installation Inspection	27	Apr 2004	LJ-1 thru LJ-1698; LW-1 thru LW-347; LL-1 thru LL-61; LM-1 thru LM-141; RLU-1 thru RLU-7, RLM-1 thru RLM-12
SC 245	-	Horizontal Stabilizer Tail De-Ice System MOSFET Contactors	30	May 2004	RJ-1 thru RJ-65; RK-1 thru RK-353; RK-354 thru RK-379
SC 246	-	Landing Performance Awareness	00	Jun 2004	RB-1 & after
SC 248	1	Cockpit Audio Anomaly	23	Sep 2004	Hawker 800XP Equipped with Collins Pro Line 21 Serials 258541, 258556, 258567 & after - RESCINDED BY SB 23-3694
SC 249	1	Spin Avoidance and Spin Recovery Characteristics	00	Mar 2006	All Beech Baron Airplanes
SC 251	-	Airstair/Cabin Door Hook Annunciator Switch Check	52	Nov 2004	FA-1 thru FA-230; FF-1 thru FF-19; FL-1 thru FL-404, FL-408
SC 252	1	Inboard Fuel Cell P/N 114-389024-1/2 with Flapper Valve Installations Reversed and Residual Drain Holes Omitted in Baffle	28	Dec 2004	UA-2, UA-3; UB-1 thru UB-74
SC 253	-	Air Conditioning Compressor Motor Module Inspection	21	Feb 2005	RB-1, RB-4 thru RB-101, RB-103 thru RB-119, RB-121
SC 254	-	Handheld Microphone Audio Jack Assembly Control Column Installation (RAC STC Number SA4900SW installed on Challenger Model CL-600 1A11, CL-600 2A12, CL-600 2B16	23	Mar 2005	1054, 1059, 1069, 1071, 1080; 3012, 3013, 3025, 3034, 3045, 3050, 3051, 3061, 3065; 5012, 5046, 5060
SC 255	-	Flight Control Column Link Assembly Inspection	27	Apr 2005	1900, 1900C, 1900C (C-12J), 1900D
SC 256	1	Left Hand and Right Hand Aft Baggage and Maintenance Bay Doors	52	May 2006	Raytheon Aircraft Model 390 Premier I, All Series

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 257	-	Main Landing Gear (MLG) Side Stay Lower Arm Lubrication	32	May 2005	All Hawker Series 1 through 1000 Airplanes
SC 258	-	Wet and Contaminated Runway Performance Awareness	92	Jun 2005	Model 390 Premier I
SC 259	-	Rockwell Collins Digital Autopilot Vertical Mode Selection Anomaly	22	Jul 2005	Raytheon Aircraft Beech Model 390, 2000, 400, 400A, Hawker 400XP, 800, 800XP and 800 (U-125A), if equipped with a Rockwell Collins APS-85, APS-850, APS-3000 OR APS-4000 Flight Control System
SC 261	-	Elevator Inspection	27	Aug 2005	UA-3, UB-1 thru UB-74, UC-1 thru UC-174, UD-1 thru UD-6, UE-1 thru UE-439
SC 262	-	Aisle Width and Emergency Egress Compliance	11	Oct 2005	ALL HAWKER SERIES 1 THROUGH 1000 AIRPLANES
SC 263	-	Inspection Of Hydraulic Lines For Possible Chafing	29	Oct 2005	BAE Series 1000A, 1000B; Hawker 1000
SC 265	-	Inspection of Flight Control System and Rigging	27	Nov 2005	LJ-1697 thru LJ-1726, LJ-1728, LJ-1729, LJ-1731 thru LJ-1739; BB-1827 thru BB-1912; BL-148, BL-149; FL-379 thru FL-423, FL-426, FL-428 thru FL-450, FL-452; FM-11
SC 266	-	Rudder Trim Tab Forward Cable Installation	55	Nov 2005	Raytheon Aircraft Beech Model 1900, 1900C, 1900C (C-12J) and 1900D All Serials
SC 267	-	390-580035-0001 Hydraulic Tube Inspection	29	Jan 2006	Raytheon Aircraft Model 390 Premier I, RB-4 through RB-49 with Kit 390-9100 Installed, RB-50 through RB-141, and RB-143 through RB-148
SC 268	-	Starter-Generator Terminal Block Connections	24	Feb 2006	Raytheon Aircraft Model 390 Premier I, Serials RB-1, RB-4 through RB-141, and RB-143 through RB-148
SC 269	-	Operations and Procedures	72	Apr 2006	All Raytheon Mitsubishi Model MU-300, MU-300-10; Beechjet Model 400, 400A; Hawker Model 400XP; Model 400T (T-1A and TX) Aircraft
SC 270	-	100 Ampere Current Limiters - Part Number UAM100	24	May 2006	All Hawker Series 1 through 1000 Airplanes
SC 271	-	Inspection of Left Engine Propeller Accumulator Oil Line for Possible Chafing	61	May 2006	Raytheon Aircraft Model 58 and G58 Baron, Serials TH-2097 through TH-2150 with Optional Propeller Unfeathering Accumulators

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 272	-	Dual Engine Power Loss	72	Aug 2006	All Raytheon Mitsubishi Model MU-300; Beechjet Model 400, 400A including Hawker 400XP); Model 400T (T-1A and TX) Aircraft
SC 273	-	Torque Application, Hydraulic Tube P/N 390-580035	29	Aug 2006	Raytheon Aircraft Model 390 Premier I, RB-4 through RB-49 with Kit 390-9100 Installed, RB-50 through RB-159
SC 274	1	Hydraulic System Status Annunciation	29	Oct 2006	Raytheon Aircraft Model 390 Premier I, Serials RB-4 through RB-159, RB-161 through 172
SC 275	-	Wing Repair Spar Lower Cap Inspection	57	Sep 2006	UA-1 & after; UB-1 & after; UC-1 & after; UD-1 & after; UE-1 & after
SC 276	-	Lap Belt Inspection and Maintenance	25	Oct 2006	All Hawker Series 800, 800XP, 850XP and 1000 Airplanes
SC 277	-	Inspection of Forward Elevator Trim Cable	27	Oct 2006	Raytheon Aircraft Beech Model 1900D, Serials UE-1 through UE-439 equipped with Optional Collins APS-65 Autopilot Systems
SC 278	-	Cabin Heater Fuel Pump, P/N 58-920054-11	24	Jan 2007	Baron 58 and G58
SC 279	1	Left Hand and Right Hand Aft Baggage and Maintenance Bay Doors	52	Nov 2007	Model 390, All Premier I/IA Aircraft. Hawker Beechcraft Corporation (HBC) is issuing this Safety Communiqué to update owners and operators concerning HBC's continuing effort to improve the aft baggage/maintenance door latch mechanism design.
SC 280	-	MS21908J6 90-Degree Fitting Installation and Torque	29	Jun 2007	MODEL 390 PREMIER I/IA, SERIALS RB-1 THROUGH RB-209 WITH HAWKER BEECHCRAFT KIT 390-3800 INSTALLED
SC 281	-	Rockwell Collins Flight Management System (FMS) and Attitude Heading Reference System (AHRS) Operational Limitations	34	Jul 2007	Models B200, B300 (350), 2000, 390, 400A, 400A(400XP), 400T (T-1A AND TX), 800XP AND 850XP, If Equipped with a Rockwell Collins FMS-850, FMS-3000, FMS-5000, OR FMS-6000 Flight Management System.
SC 282	-	Interference Between Elevator Control System and Electrical Wiring Harness	27	Aug 2007	HAWKER BEECHCRAFT MODEL G36 BONANZA AND G58 BARON AIRPLANES, ALL SERIALS
SC 283	-	Hydraulically Actuated Brake Control System	32	Aug 2007	390 Premier I/IA, Serials RB-160 through RB-202, and Serials RB-4 through RB-159 with kit 390-5801-0001 installed per Optional Service Bulletin No. 32-3809

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 285	-	Hydraulic Power Pack Low Liquid Level Sensor Functional Test	29	Dec 2007	Hawker Beechcraft Model 1900 Airplanes, Serial Number UA-3; Model 1900C, Serial Numbers UB-1 Through UB-74; UC-1 Through UC-174 and 1900C(C-12J), UD-1 through UD-6; 1900D Airliners UE-1 Through UE-439.
SC 286	-	Main Landing Gear Keel Inspection	32	Feb 2008	HAWKER BEECHCRAFT MODEL 1900 AIRPLANES, SERIAL NUMBER UA-3, MODEL 1900C, SERIAL NUMBERS UB-1 THROUGH UB-74; UC-1 THROUGH UC-174 AND 1900C(C-12J), SERIAL NUMBERS UD-1 THROUGH UD-6; 1900D AIRLINERS, SERIAL NUMBERS UE-1 THROUGH UE-439.
SC 287	-	Wing Jack Pad Adapter Attachment Hardware	25	Jan 2008	Hawker Beechcraft Model 390 Premier I/IA, All Serials
SC 288	-	Lifting and Shoring - Maximum Jacking Weight	07	Jan 2008	Hawker Beechcraft Model 390 Premier I/IA, All Serials
SC 289	-	Rupture of P/N WKA 30773 Oxygen System Filter Bursting Discs	35	Feb 2008	HAWKER BEECHCRAFT MODEL 800XP AND 850XP, SERIALS 258800 AND SUBSEQUENT; MODEL 800 (U-125A), SERIAL 258735; MODEL 900XP, SERIALS HA-0001 AND SUBSEQUENT. DH/BH/HS/BAe 125 SERIES 400 POST MOD 252036 OR SERVICE BULLETIN 35-16, SERIES 600, 700, 800, 800XP, AND 850XP WITH OXYGEN DISCS INSTALLED, WHICH WERE PURCHASED SINCE JUNE 1, 2006.
SC 290	-	Tail De-ice Boot Pneumatic Supply Tubes	30	Feb 2008	HAWKER BEECHCRAFT MODEL B200, SERIALS BB-1926, BB-1978, BB-1988 THROUGH BB-2000; MODEL B300, SERIALS FL-427, FL-493, FL-500 THROUGH FL-573, MODEL B300C, SERIALS FM-14 THROUGH FM-18; AND MODEL B200GT, SERIALS BY-1 THROUGH BY-26 WITH KEITH PRODUCTS AIR CONDITIONING SYSTEM INSTALLED.
SC 291	-	Inspection of Cabin Barometric Pressure and Cabin Altitude High Switches	21	Apr 2008	HAWKER BEECHCRAFT MODEL 390 PREMIER I/IA, SERIALS RB-1, RB-4 THROUGH RB-235.
SC 292	-	Inspection for Brake Flammable Fluid Tube Assembly Chafing Damage Below the Nose Baggage Compartment	24	Apr 2008	HAWKER BEECHCRAFT MODEL G58 BARON, SERIALS TH-2125 THROUGH TH-2170.
SC 293	-	Inspection for Indication of Fuel Leak in the Fuel Injection System	5	Apr 2008	ALL HAWKER BEECHCRAFT MODEL G58 BARON AND MODEL G36 BONANZA AIRPLANES THAT HAVE NOT COMPLETED A 100-HOUR OR ANNUAL INSPECTION

Communique #	Rev No	Description	Chapter	Date	Effectivity
SC 295	-	Main Landing Gear (MLG) Upper Casing P/N 25-8UM169-5/-6 Inspection	32	Jul 2008	HAWKER BEECHCRAFT SERIAL NUMBERS 258474, 258483, 258463, 258294, 258295, 258298, AND 258510 WITH P/N 25-8UM169-5 LEFT MLG UPPER CASINGS INSTALLED AND SERIAL NUMBERS 258293, 258308, 258483, 258289, 258007, 258731, 258299, AND 258012 WITH P/N 25-8UM169-6 RIGHT MLG UPPER CASINGS INSTALLED
SC 296	-	Single Point Refueling (SPR) Receptacle Fuel Leakage	28	Aug 2008	RB-1, RB-4 and after
SC 297	-	Left and Right Main Landing Gear Extension / Retraction Actuator Rod End Bearing Inspection	32	Sep 2008	Hawker Beechcraft Model 390 Premier 1/1A, Serials RB-1 through RB-248
SC 298	-	Outboard Wing Fire Potential Due To Fuel Leaks And Electrical Wire Chafing		Oct 2008	Hawker Beechcraft Baron and Bonanza Models, All Serials