



**GARMIN G1000 SOFTWARE CONFIGURATION MATRIX
FOR THE MODEL A36/G36**

The following is the approved configuration of GARMIN hardware and it's associated software. This document may be subsequently revised by Service Bulletins and/or product upgrades. To confirm the approved configuration for your airplane visit

http://www.raytheonaircraft.com/service_support/publications.asp or call Raytheon Aircraft Customer Support at 1-800-429-5372.

G1000 A36/G36 Code Loader Card, Garmin Part Number 010-00458-04 (Installs G1000 System Software Version 0458.04)				
Description	Compatible LRU P/N's	System Status Page Name	Software	
			P/N	VER.
GTX 33 Mode S Transponder	011-00779-01	GTX1-GIA1	006-B0172-xx	4.02
		GTX1-GIA2		
GEA 71 Engine/Airframe Unit	011-00831-00	GEA1-GIA1	006-B0193-04	2.06
		GEA1-GIA2		
GDC 74A ADC	011-00882-00	GDC1-GIA1	006-B0261-03	2.05
		GDC1 FPGA	006-C0055-00	01.05
GMU 44 Magnetometer	011-00870-00	GMU1	006-B0224-00	2.01
		GMU1 FPGA	006-C0048-00	2.00
GDU 1040 PFD	011-00972-03	PFD1	006-B0319-31	5.01
GDU 1043 MFD	011-01079-00	MFD1	006-B0319-31	5.01
GIA 63 No. 1 (1)	011-00781-01	GIA1	006-B0190-22	3.02
		GPS1	006-B0093-xx	3.01
		COM1	006-B0081-xx	7.00
		NAV1	006-B0082-xx	4.00
		GS1	006-B0083-xx	3.00
GIA 63 No. 2 (1)	011-00781-01	GIA2	006-B0190-22	3.02
		GPS2	006-B0093-xx	3.01
		COM2	006-B0081-xx	7.00
		NAV2	006-B0082-xx	4.00
		GS2	006-B0083-xx	3.00
GRS 77 AHRS	011-00868-10	GRS1-GIA1	006-B0223-02	2.03
		GRS1-FPGA	006-C0049-00	02.00

10/13/2005

P/N 36-590002-73

1 OF 2

GARMIN G1000 SOFTWARE CONFIGURATION MATRIX
FOR THE MODEL A36/G36

GMA 1347 Audio Panel	011-00809-00	GMA1-GIA1	006-B0203-06	2.07
		GMA1-GIA2		
		GRS1 MV DB	006-D0159-00	2000.00
GDL 69A Data Link	011-00987-00	GDL69	006-B0317-10	3.00.00
GSA 81 Autopilot Servo –Qty 4	011-00878-00	(3)	006-B0398-12	2.05
		(2)	006-D0372-01	2.01

- (1) Garmin Service Bulletin 0418 must be complied with.
- (2) All LRU entries that begin with GFC1 CERT or CFC2 CERT.
- (3) All LRU entries that begin with GSA.